




This response card should be provided to the recipient of the package the indicator is placed in; enabling them to obtain proper reading of the indicator. Please call for additional usage information.



HCL #8208-01

MonitorMark™ Time/Temperature Indicator TTI - 9860H

Response Temperature 31°C (88°F)



The above illustration shows how to use the runout indexes on the other side of this card to estimate the time a particular activated indicator has been exposed above its Response Temperature.

From the readings on the two index scales and some general knowledge about the exposure conditions, one can estimate time/temperature exposures.



Identification and Converter
Systems Division

3M Center, Building 220-7W-03
St. Paul, MN 55144-1000

REORDER FROM

HEALTH CARE LOGISTICS
CALL FREE 1-800-848-1633
FAX FREE 1-800-447-2923

HCL #8208-01




This response card should be provided to the recipient of the package the indicator is placed in; enabling them to obtain proper reading of the indicator. Please call for additional usage information.



HCL #8208-01

MonitorMark™ Time/Temperature Indicator TTI - 9860H

Response Temperature 31°C (88°F)



The above illustration shows how to use the runout indexes on the other side of this card to estimate the time a particular activated indicator has been exposed above its Response Temperature.

From the readings on the two index scales and some general knowledge about the exposure conditions, one can estimate time/temperature exposures.



Identification and Converter
Systems Division

3M Center, Building 220-7W-03
St. Paul, MN 55144-1000

REORDER FROM

HEALTH CARE LOGISTICS
CALL FREE 1-800-848-1633
FAX FREE 1-800-447-2923

HCL #8208-01