


This response card should be provided to the recipient of the package the indicator is placed in; enabling them to obtain proper reading of the indicator. Please call for additional usage information.

**3M**

HCL #8205-01


**MonitorMark™  
Time/Temperature Indicator  
10I**

**Response Temperature 10°C (50°F)**



Hrs. at 12°C (54°F) 0 5 10 20 30 40 50

Hrs. at 23°C (73°F) 0 5 10 20 30 40



Hrs. at 12°C (54°F) 0 5 10 20 30 40 50

Hrs. at 23°C (73°F) 0 5 10 20 30 40

The above illustration shows how to use the runour indexes on the other side of this card to estimate the time a particular activated indicator has been exposed above its Response Temperature.

From the readings on the two index scales and some general knowledge about the exposure conditions, one can estimate time/temperature exposures.

**3M**

**Identification and Converter  
Systems Division**

3M Center, Building 220-7W-03  
St. Paul, MN 55144-1000

**REORDER FROM  
HEALTH CARE LOGISTICS  
CALL FREE 1-800-848-1633  
FAX FREE 1-800-447-2923  
HCL #8205-01**


This response card should be provided to the recipient of the package the indicator is placed in; enabling them to obtain proper reading of the indicator. Please call for additional usage information.

**3M**

HCL #8205-01


**MonitorMark™  
Time/Temperature Indicator  
10I**

**Response Temperature 10°C (50°F)**



Hrs. at 12°C (54°F) 0 5 10 20 30 40 50

Hrs. at 23°C (73°F) 0 5 10 20 30 40



Hrs. at 12°C (54°F) 0 5 10 20 30 40 50

Hrs. at 23°C (73°F) 0 5 10 20 30 40

The above illustration shows how to use the runour indexes on the other side of this card to estimate the time a particular activated indicator has been exposed above its Response Temperature.

From the readings on the two index scales and some general knowledge about the exposure conditions, one can estimate time/temperature exposures.

**3M**

**Identification and Converter  
Systems Division**

3M Center, Building 220-7W-03  
St. Paul, MN 55144-1000

**REORDER FROM  
HEALTH CARE LOGISTICS  
CALL FREE 1-800-848-1633  
FAX FREE 1-800-447-2923  
HCL #8205-01**